This is a reproduction of a library book that was digitized by Google as part of an ongoing effort to preserve the information in books and make it universally accessible.



https://books.google.com



DETAILED HISTORY OF THE RAILWAYS

IN THE

SOUTH AFRICAN WAR

1899-1902

VOL. JI.-ILLUSTRATIONS


All Rights Reserved

CHATHAM:
ROYAL ENGINEERS INSTITUTE

1904

AGENTS: W. AND J. MACKAY AND CO., LTD., CHATHAM

Digitized by Google





FRONTISPIECE. RAILWAY MAP — o F — SOUTH AFRIC Scale. Imperial Military Railways shown Orange A C Piquetberg Rd. BACESTER Swellendon

DETAILED

HISTORY OF THE RAILWAYS

IN THE

SOUTH AFRICAN WAR

1899—1902

VOL. II.-ILLUSTRATIONS

All Rights Reserved

CHATHAM:

ROYAL ENGINEERS INSTITUTE, Chatham

1904

AGENTS: W. AND J. MACKAY AND CO., LTD., CHATHAM

Transfordation decades

PRINTED BY
W. AND J. MACKAY AND CO., LTD., CHATHAM.



Transportation
Library
HE
3419
.S7
R89
v.2

LIST OF PHOTOGRAPHS.

NUMBER.	SUBJECT.	REFERENCE TO PAGE OF TEXT.
	PART L-CAPE GOVERNMENT RAILWAYS.	
	CHAPTER IV.—REPAIR OF LINES DAMAGED BY ENEMY.	
I	Modder R. bridge, Kimberley line; view from South bank showing damage by enemy	29
2	Vaal R. bridge, Fourteen Streams, Kimberley-Mafeking line; showing damage by enemy	30
	PART II.—NATAL GOVERNMENT RAILWAYS.	
	CHAPTER V.—REPAIR OF LINES DAMAGED BY ENEMY.	
3	Newcastle; water tank destroyed by enemy	. 57
4	Tugela R. bridge, Colenso; showing damage by enemy	59
5	Do.; deviation railway bridge and footbridge	63
6	Do.; "Princess Christian" hospital train crossing	
	deviation bridge	"
7	Sunday R. bridge; showing damage by enemy	59
8	Ingogo R. bridge; do	,,
9	Incandu R. bridge; do	,,
11	Waschbank R. bridge; do Zand Spruit bridge; showing damaged girders supported on	,,
	trestles Laing's Nek tunnel; showing damage by enemy at south end	,,
12	Do.; south entrance cleared	64
13	Vaal R. Bridge, Standerton, Elandsfontein-Natal line; showing	"
14	damage by enemy	50 65
15	Do.; semi-permanent bridge	59, 65 65
	PART IIITHE RAILWAY PIONEER REGIMENT.	
	CHAPTER II.—ACCOUNT OF WORK DONE.	
• 6	Orange R. bridge, Norval's Pont; showing damage by enemy	5 0 0-
16	Do.; near view of destroyed pier and span	79, 80
17	Do.; reconstruction; inside view of girders before	,,
10	lifting on trollies for launching	18
19	Do.; launching girders on reconstruction	79
20	Do.; showing Bate's girders at north end	. 81
21	Do.; repaired; showing low level deviation along-	; !
22	side and pontoon bridge in background Orange R. bridge, Bethulie; showing damage by enemy and	82
	deviation bridge	,,
	(For Vet R., Zand R., and Vaal R. bridges see below).	

NUMBER.	SUBJECT.	REFERENCE TO PAGE OF TEXT.
	PART IV.—IMPERIAL MILITARY RAILWAYS.	
	CHAPTER II.—ENGINEERING DEPARTMENT.	
	I.—Work in Orange River Colony.	
23	Modder R. bridge, Glen, Bloemfontein-Pretoria line; bridge	
2.	of crib piers and trussed beams on deviation	122
24	Vet R. bridge; showing damage by enemy Do.; skew bridge on deviation	124
25 26	De la companya de la	,,
27	Do.; semi-permanent bridge Do.; girders waiting to be drawn out during recon-	82
21	struction	128
28	Do.; locomotive drawing girders out	1
29	Do.; launching girders	"
30	Doorn Spruit; temporary bridge	,, I 2 4
31	Zand R. bridge; showing damage by enemy	84, 124
32	Do.; semi-permanent bridge	84
33	Valsch R. bridge; showing damage by enemy	125
34	Do.; launching girders during reconstruction	127
35	Rhenoster R. bridge; 2nd temporary bridge, replacing bridge	
	burnt by enemy	126
36	Vaal R. bridge, Vereeniging; showing damage by enemy	85,126,129
37	Do.; low level bridge on deviation	126
38	Do.; launching girders during reconstruction	85
39	Taaibosch Spruit bridge; girders being drawn up for permanent	
:	reconstruction, temporary bridge behind	129
	II.—Work in the Transvaal.	
40	Zuikerbosch Spruit bridge, Elandsfontein-Natal line; showing	
40	damage by enemy	130
41	Bronkhorst Spruit bridge, Pretoria-Delagoa Bay line; showing	
4.	damage by enemy	,,
42	Wilge R. bridge; showing damage by enemy	,,
43	Do.; 50-foot span of trussed beams	,,
44	Krokodil Poort; temporary bridge with crib piers	131
45	Kaap R. bridge, Kaapmuiden; showing bridge damaged by	
	enemy, deviation bridge, and wreck of train	131, 132
	CHAPTER IV.—LOCOMOTIVE DEPARTMENT,	
		ł
46	Zand R., Bloemfontein-Pretoria line; boiler of pumping engine,	
	blown up by enemy	158
	PART V.—ARMOURED TRAINS.	
	CHAPTER III.—DETAILED DESCRIPTION OF AN	
	ARMOURED TRAIN.	ŀ
47	First pattern gun truck, No. 1 Armoured train	244
48	First pattern of armoured engine	245
49	New pattern gun truck for 12-pounder Q.F. gun	243
50	9.2-inch gun mounted on engine frame	244
51	6-inch gun truck	,,
52	No. 1 Train; armament:—two 12-pounder Q.F., three	
<i>3</i>	·303 Maxims	236, 244
		1


NUMBER.	SUBJECT.	REFERENCE TO PAGE OF TEXT
	PART V.—Continued.	
	CHAPTER III.—Continued.	
53	No. 2 Train; one 12-pounder Q.F., two 303 Maxims	244
54	No. 17 Train; do. do	,,
55	No. 18 Train; one 12-pounder Q.F., two 450 Maxims	236, 244
56	6-pounder gun truck on No. 11 Train	244
57	New pattern bogie on No. 12 Train, with 6-pounder gun and	
	infantry	243
58	No. 20 Train; armament:—one double-barrel Nordenselt, one	
	303 Maxim, one 3-pounder Q.F	,,
59	No. 16 Train; 3-pounder gun in turret	,,
60	Do.; one 3-pounder, two 303 Maxims	244
16	Pompom truck on No. 3 Train	,,

LIST OF PLATES.


ļ		BEFFBENCE
NUMBER.	SUBJECT.	TO PAGE
	Sobject.	OF TEXT.
1 2	FRONTISPIECE. General Map of Railways in South Africa. PART I.—CAPE GOVERNMENT RAILWAYS. CHAPTER IV.—REPAIR OF LINES DAMAGED BY ENEMY. Map of C.G.R. from Orange R. to Mafeking Modder R. bridge, Kimberley line, showing damage by enemy and semi-permanent repairs Do.; Proposition of deviation, and bridge	28 28, 29
4	on same Kimberley-Mafeking line; types of semi-permanent repairs to	,,
•	small bridges and culverts	29
5 6	Do. do Vaal R. bridge, Fourteen Streams, Kimberley-Mafeking line;	,,
	plan of deviation	30
7	Do.; temporary bridge on deviation	,,
8	Orange R. bridge, Norval's Pont; plan and section of deviation	39
	PART IINATAL GOVERNMENT RAILWAYS,	1
	CHAPTER I.—GENERAL DESCRIPTION.	
9	Sectional diagram of main line	49
9		49 50
-	Sectional diagram of main line	1
-	Sectional diagram of main line Types of rolling stock	1
10	Sectional diagram of main line Types of rolling stock	50
10	Sectional diagram of main line	50
10	Sectional diagram of main line	50 55 56
10 11 12 13 14	Sectional diagram of main line	50 55 56 76 63
10 11 12 13 14 15	Sectional diagram of main line	50 55 56
10 11 12 13 14 15 16	Sectional diagram of main line	50 55 56 ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
12 13 14 15 16	Sectional diagram of main line	56 ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
10 11 12 13 14 15 16	Sectional diagram of main line	56 ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
12 13 14 15 16	Sectional diagram of main line	55 56 ,,, 63 56, 57 ,, 65
12 13 14 15 16 17	Sectional diagram of main line	56 ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
10 11 12 13 14 15 16 17 18	Sectional diagram of main line	55 56 3 56, 57 3 65


NUMBER.	SUBJECT.	REFERENCE TO PAGE OF TEXT.
ı	PART IIITHE RAILWAY PIONEER REGIMENT.	
	CHAPTER II.—ACCOUNT OF WORK DONE.	
22	Oorlog's Poort bridge, Cape Colony; semi-permanent trestle	1
22	bridge	70
23	Do.; details of trestles	79
24	Orange R. bridge, Norval's Pont; semi-permanent reconstruction;	,,
	aerial tram and trestles for launching girders	79, 81
25	Do.; details of aerial tram	79
26	Do.; details of semi-permanent trestles for Bate's	• /
•	girders	81, 82
27	Do.; details of trestles for launching girders	81
28	Orange R. bridge, Bethulie; plan of deviations	82
29	Do.; sections of deviation over road bridge and low	
i	level deviation	,,
30	Do.; temporary bridge on low level deviation	,,
31	Vet R. bridge, Bloemfontein-Pretoria line; semi-permanent	1
	trestle bridge	,,
32	Do.; details of trestles	,,
33		, ,,
2.4	(See also Nos. 45, 46 and 47). Zand R. bridge; aerial tram and semi-permanent trestles	84
34	Do.; details of trestles	
35	Do. do	,,,
37	Do.; details of trussed beams	,,
) 31 	(See also Nos. 49 and 50).	,,, '
38	Vaal R. bridge, Vereeniging; damaged bridge and re-arrangement	1 ,
	of girders	85, 129
39	Do.; semi-permanent trestles at south end	86, 129
40	Do.; details of trestles	۱ ,,
1	(See also Nos. 61 and 62).	0.6
41	Bate composite girders for portable bridges	86
i !	PART IVIMPERIAL MILITARY RAILWAYS.	
1	CHAPTER II.—ENGINEERING DEPARTMENT.	
	I.—Work in Orange River Colony.	
42	Modder R. bridge, Glen, Bloemfontein-Pretoria line; plan and	
	section of deviation	123
43	Do.; temporary bridges on deviation	,,
44	Do.; damaged bridge, and launching girders on	
	new bridge	127
45	Vet R. bridge; plan and section of deviation	124
46 47	Do.; skew bridge on deviation Do.; minor bridges on deviation	,,
47	(See also Nos. 31, 32 and 33).	,,
48	Doorn Spruit; temporary bridge on deviation	
49	Zand R.; plan and section of deviation	,,
50	Do.; temporary bridges on deviation	,,
	(See also Nos. 34, 35, 36 and 37).	"
51	Valsch R. bridge; elevation of damaged bridge	125
52	Do.; plan and section of deviation	,,,
53	Do.; temporary bridge on deviation	,,
54	Do.; bridge at A on deviation	,,
55	Do.; semi-permanent trestle bridge	127, 128
56	Do. do. details of trestles	"
57	Rhenoster R. bridge; plan and section of deviation	125
58	Do.; 1st temporary bridge on deviation Do.: 2nd do	"
59 60	Do.; 2nd do Taaibosch Spruit; temporary bridge on deviation	126
	- amooson optuit, temporary bridge on deviation	125

NUMBER.	SUBJECT.	REFERENCE TO PAGE OF TEXT.
	PART IV.—Continued.	
	CHAPTER II.—Continued.	
	I.—WORK IN ORANGE RIVER COLONY.—Continued.	
61	Vaal R. bridge, Vereeniging; plan and section of deviation	126
62	Do.; temporary bridge on deviation	,,
63	(See also Nos. 38, 39 and 40). Hennops R. bridge, Irene; bridge as left by enemy	
ύ <u>3</u> ύ4	Do.; temporary bridge on deviation	,,
65	Vredefort Road to Elandsfontein; standard dimensions for	"
- 3	bridge repairs	129
	II.—Work in the Transvaal.	
66	Blesbok Spruit, Elandsfontein-Natal line; bridge as left and	
6 -	as reconstructed	130, 133
67 68	Zuikerboschrand Spruit; temporary bridge on deviation	130
00	Do.; damaged bridge and reconstruction of girders	130, 133
69	Bronkhorst Spruit, Pretoria-Delagoa Bay line; temporary bridge	130, 133
· • •	on deviation	130
70	Kilomètre 401; temporary repairs on 5-mètre culvert	,,
71	Wilge R. bridge; bridge of trussed beams on deviation	,,
72	Godwan R.; temporary bridge	131
73	Krokodil Poort; temporary bridge	,,
74	Do.; semi-permament bridge	134
75	Kaap R. bridge, Kaapmuiden; temporary bridge on deviation	132
76	Do.; damaged bridge and semi-permanent repair	131, 134
77	Do.; details of semi-permanent trestles	134
78	Malalane bridge; temporary bridge on deviation and semi-	
70	permanent trestle bridge Hector Spruit; do. do.	132, 134
79 80	Kaap R. bridge, Avoca; bridge as left by enemy	132
81	Do.; plan and section of deviation	,,
82	Do.; temporary bridge on deviation	,,
83	Pienaars R. bridge, Pretoria-Pietersberg line; temporary skew	1 "
	bridge on deviation	,,
84	Bank bridge, Elandsfontein-Klerksdorp line; semi-permanent	
	bridge	135
85	Koekemor bridge; do.; do.	,,
86	Kilomètre $204\frac{1}{2}$; do.; do	,,
87	Frederiksstad bridge; do.; do	,,
	PART V.—ARMOURED TRAINS.	
	CHAPTER III. DETAILED DESCRIPTION OF AN ARMOURED TRAIN.	
88	Arrangement of No. 1 Train	242
89	12-pounder Q.F. gun truck (New pattern)	173, 243
90	12-pounder Q.F. gun truck and Maxim truck (Old type); plans	244
91 .	Do. do. elevations	
92	Escort truck	250
93	Armoured brake van	,,




Modder R. Bridge, Kimberley line. View from south bank, showing damage by enemy.








Tugela R. Bridge, Colenso, Natal. Showing damage by enemy. Fort Wylie in background.





Tugela R. Bridge, Colenso, Natal. Deviation railway bridge and footbridge; looking South.

















Digitized by Google



Laing's Nek Tunnel, Natal.


Showing damage by enemy at South end.






Digitized by Google

Vaal R. Bridge, Standerton, Elandsfontein—Natal line. Semi-permanent reconstruction.









Orange River Bridge, Norval's Pont.

Reconstruction; inside view of pair of girders before lifting on trollies for launching.







Digitized by Google

Orange R. Bridge, Norval's Pont, repaired. Showing low level deviation alongside and pontoon bridge in background.

Orange R. Bridge, Bethulie. Showing damage by enemy and low level deviation.




Modder R. Bridge, Glen, Bloemfontein—Pretoria line. Bridge of crib piers and trussed beams on deviation.




Vet R. Bridge, Bloemfontein—Pretoria line. View from North bank, showing damage by enemy.

Vet R. Bridge, Bloemfontein—Pretoria line. Skew bridge on deviation.




Digitized by Google


Vet R. Bridge, Bloemfontein—Pretoria line. Girders waiting to be drawn out during reconstruction.



Vet R. Bridge, Bloemfontein—Pretoria line.
Launching girders during reconstruction.




Zand R. Bridge, Bloemfontkin—Pretoria line. View from South bank, showing damage by enemy.




Zand R. Bridge, Bloemfontein—Pretoria line. Semi-permanent reconstruction.


Valsch R. Bridge, Bloemfontein-Pretoria line. Showing damage by enemy.



Rhenoster R. Bridge, Bloemfontein—Pretoria line. Second temporary bridge, replacing bridge burnt by enemy.




Vaal R. Bridge, Vereeniging, Bloemfontein—Pretoria line. Showing damage by enemy.




Vaal R. Bridge, Vereeniging, Bloemfontein—Pretoria line View from north bank of low level bridge on deviation.

Vaal R. Bridge, Vereeniging, Bloemfontein—Pretoria line. Launching girders on reconstruction.




Taaibosch Spruit Bridge, Bloemfontein—Pretoria line. Girders being drawn up for permanent reconstruction; temporary bridge behind.




Digitized by Google


Bronkhorst Spruit Bridge, Pretoria—Delagoa Bay line. Showing damage by enemy.

Wilge R. Bridge, Pretoria—Delagoa Bay line. Showing damage by enemy.







Krokodil Poort Bridge, Pretoria—Delagoa Bay line. Temporary bridge with crib piers.




Kaap R. Bridge, Kaapmuiden, Pretoria—Delagoa Bay line. Showing bridge damaged by enemy, deviation bridge, and wreck of train.












Digitized by Google



9.2-inch Gun mounted on engine frame.



Digitized by Google



No. 1 Armoured Train.

C.O. Lieut. A. G. T. Cusins, R.E. 2nd Officer. Lieut. Beynon, C.G.A.


Armament — 2 12-pounder Q.F. 3 ·303 Maxims.

No. 2 Armoured Train.

C.O. Capt. A. M. Henniker, R.E. 2nd Officer... 2nd Lieut. Jickell, R.G.A.

Armament—1 12-pounder Q.F. 2 ·303 Maxims.

Digitized by Google




No. 17 Armoured Train.

Armament—1 12-pounder Q.F. 2 ·303 Maxims.

C.O. Major C. S. Prichard, Northampton Regt. 2nd Officer.. Capt. Bedford, R.G.A.


Digitized by Google




No. 18 Armoured Train.

C.O. Lieut. Baring, Coldstream Guards. 2nd Officer... Lieut. Murray, R.G.A.

Armament—112-pounder Q.F. 2 450 Maxims.






New pattern bogie on No. 12 Armoured Train With 8-pounder gun and Infantry.


No. 20 Armoured Train.

C.O. Lieut. Russell, 4th Scottish Rifles. 2nd Officer .. Lieut. Brunton, K.O. Scottish Borderers.


Armament—I double-barrel I" Nordenfelt. I :303 Maxim. I 3-pounder Q.F.



No. 16 Armoured Train, before alteration. With 3-pounder gun in turret.



Pompom Truck on No. 3 Armoured Train.




Digitized by Google


Officer in Charge: Capt. W. D. 1 Working Party: 8th (Railwav)


31st (Fortress


Time taken:


110 days (del girder pie













Officer in Charge: Capt. F. (
Working Party: Part of W
Time taken: 32½ hours.


TYPES OF REPAIRS TO CULVERTS. KIMBERLEY-MAFEKING LINE.

Scale - 8 Feet = 1 Inch.




Officer in Charge: Capt. F. G. Fuller, R.E.
Working Party: Part of Western Field Railway Section.
Time taken: 33½ hours, including one other culvert and one
set of points and crossings.





VAAL R. BRIDGE, FOURTEEN STREAMS.

KIMBERLEY- MAFEKING LINE.



Infantry varied from 150 to 700.


PLAN OF DEVIATION.


Scale 20 Chains-1 Inch.


Officer in Charge:


Working Party for Bridge
and Deviation 200 Info
300 Nativ
Time taken:

11 days, f
Deviat









STRAIGHTS & CURVES TO CHARLESTOWN 300% 460 Curves 100 Curves 0 35.78 .49 2.54 56.01 .20 48.80 - MOUNT PROSPECT 36.94 . 96 18.25 28.80 Reversing Stations 2. ELANDS'LAAGTE 5000 4500 4000 3500 3000 2500 2000 1500 1000 500 RULING GRADES LOCO TANKS P.L'S. LENGTINS 300% Lang's Nek Mount Prospect 213/2 Wessels Het 304 Charlestown Reversing Stations 2

BLE

NATAL GOVERNMENT RAILWAY.


ARRANGEMENT OF COACHES IN HOSPITAL TRAIN.

GINE	BRAKE	VAN -	2ºº CL. CORR.	2ºº CL . CORR .	IST CL.CORR.	- 19º CL .CORR.	2 MO CL.CORR.	2ºº CL . CORR - KITCHEN	
2′ 0″			04' o"	24/2		24'2"	3:04'0'	34'.0'25'.0'	7
0.0	4 ×36.	6 1	·34.0	H	*34.0X	K34.0	×34.0	K34.0	ېد


na. 4cmt. 16 tons. 6cmt. 14 tons. 9cmt. 14 tons. 9cmt. 16 tons. 12cmt. 16 tons. 12cmt. 14 tons. 9cmt. 14 tons. 9cmt. 8tons. 8cmt.

Total weight approx + 162 tons
Total length approx + 320 f?
Total Nº of sick +98 Lying-down Cuses.

GENERAL ARRANGEMENT.




DETAIL OF 2" CLASS CORRIDOR CARRIAGE.




DETAIL OF KITCHEN CAR.

NATAL GOVERNMENT RAILWAYS.

TYPE OF TEMPORARY BRIDGE ERECTED BY N.G.R. RECONSTRUCTION DEPT.



ANTZ.




NOTE: Each of the treatles in the bed of the river was locked down at each end of the sill by wire rope to eyebolts sunk into the rock.




TUGELA RIVER BRIDGE, COLENSO.

NATAL LINE.

PLAN AND SECTIONS OF DEVIATIONS.





- SECTION OF LINES ACROSS TUGELA taken from N.G.R. Official Sections
Distances Approximate


SECTION OF DRIGINAL LINE

APPROX. SECTION OF DEVIATION & BRIDGE IN COURSE OF CONSTRUCTION

----- APPROX. SECTION OF DEVIATION WITH MAX. GRADE OF I W 25

BRIDGE.

O-FOOT CLEAR SPANS.




 $\mathsf{Digitized} \; \mathsf{by} \; Google$


BRIDGE.


STREAM

O-FOOT CLEAR SPANS.



Digitized by Google






INGAGANE RIVER BRIDGE.


NATAL LINE.

TRESTLE STAGING FOR ERECTING 100-FOOT CLEAR SPANS.

Scale-4 Feel=1 Inch.



Carried out by Nata
"A"
17th




STANDERTON.


LE BRIDGE.

ıch.

ew Girders without stopping Traffic.




LES.




OGE.


APE COLONY.

ITLE BRIDGE.




E.
neer Regiment.







Digitized by Google


PLATE 25.









DETAILS OF TROLLEY.





'TRESTLE, NORTH SPAN -




Digitized by Google

ORANGE R.BRIDGE, BETHULIE. BLOEMFONTEIN LINE.

PLAN OF DEVIATIONS


Scale, 12 Chains - 1 inch.




EIN L

DEVIA

, A.B.C. PLATE 28.





4 Chains = 1 Inch.

. 20 Feet = 1 "

OAD BRIDGE, BI
MFONTEIN LINE.
MPORARY LOW LEVEL D

PLATE 30.

Scale 20 Feet - 1 Inch.

Fifteen
Spans.


Av. 22'. 8'.
each.

ly used by C.G.K on first consticonsequently their bearing on rive BRIDGE.


TORIA LINE.


STLE BRIDGE.


proximately





ES.












ZAND RIVER BRI BLOEMFONTEIN-PRETORIA DETAILS OF TRUSSED E

Scale-1 Inch=1 Foot.



HIGING.

F GIRDERS.

SOUTH SOUTH

O. R. C.

HE ENEMY


n same manner

CIRDERS


ENIGING.

E.


TH END.




VAAL RIVE BLOEI DETAILS O




TRESTLE D ---





SECTION ADAPTED FOR 4'.84 ADAPTED FOR 2'.6" GAUGE.

Maximum distributed dead load im distributed dead load80 tons
do. single load as on one ux single load as on one and pair of wheels axle and pair of wheels8 ,
do. rolling load at speed of load80 tons



Lieut. H.W. Buckle, R.E.
127th Field/Company, R.E.
129th " Charge:

100 Infantry. Party for


Party for 100 man.


Veriation 4 Civilian Carpenters.


4 "Placelayers.


60 Natives.

n to construct Bridges, and 1 Mile 56 Chains Deviation—17 Days y, as Army was halted with Advance Force here.









__ SECTION OF TRUSS AT A.B. ___

r in Charge: Lieut. H. W. Buckle, R.E.


½ 7th (Field) Company, R


100 Infantry.

4 Civilian Carpenters and 4

60 Natives:


laken to construct Bridges and 1 mile eviation—17 days. (Army was halted a no urgency).








 \boldsymbol{B}


Length of Deviation Maximum Gradient Minimum Curve 1 Mile 18 Chains 1 in 36 29 5 Chains Hadius














Officer in Charge: Working Party:

Time taken:

Length of Deviation: 1 Mil RAD: 20 CHS.

Minimum Curve 5 Ch.

Lieut. H.A. Micklem. D.S.O., R.E.

Theer, 40 Non-Commissioned Officers & Men 10th (Railway) Company R.E.

Theer, 47 " " " " 20th (Fortress) Company R.E.

Theer, 47 " " " 42th (Fortress) Company R.E.

E. Officers.

Infantry details.


Natives.

Civilian Gangers and 2 Permanent Way Inspectors.


The certic Light Section Volunteer Engineers under Capt. F.L. Lloyd R.E.

Cantry, averaging 300

Let temporary Bridges and 1 Mile 44 Chains Deviation, 5 days 10 hours.



Officer in Charge : Lieut H.A. Mice Working Farty 1 Officer, 40 N.C 20 N.C.O. & Mer Electric Light S 4 R.E. Officera 33 Infantry det 2 Givilian perma 30 " gange 750 Natives Infantry party. Time taken for bridges and 1 mile See also Plates 34, 35, 36







PLATE 53.




VALSCH R. BRIDGE.

BLOEMFONTEIN-PRETORIA LINE.

TRESTLE BRIDGE AT A ON DEVIATION.

Scale-8 Feet=1 Inch.



ECONST






PLATE **56**. BENT

BLOEMFONTEIN-PRETORIA LINE. VALSCH R. BRIDGE.

Scale-8 Feet=1 Inch.






RHENOSTER R. BRIDGE BLOEMFONTEIN_PRETORIA LINE

PLAN & SECTION OF DEVIATION.

Horizontal Scale _ 8 Chains = 1 Inch Vertical Scale _ 40 Feet = 1 Inch



Length of Deviation _57 Chains. Maximum Gradient _1 in 61.33. Officer in Charge Lieut II.A. Micklem. D.S.O. RE.


5 Officers 150 Non-Commissioned
Officers & Men. R.E.

Working Party.

55 Infantry details.

600 Natives.

Time tuken for Bridge & Deviation 5 days 121/2 hours




Officer in Charge: Lieut. H. 2


Working Party: 5 Officers,

55 Infantry 600 Natives

Time taken for Bridge and De

This Bridge was destroyed by by a Trestle Bridge.






RID


LIN


MEATIO

Tu




TRANSVAAL.






HENNOPS R. BRIDGE, IRENE. BLOEMFONTEIN-PRETORIA LINE.

Scale -- 12 Feet=1 Inch.



BRIDGE AS LEFT BY THE ENEMY
DOTTED PORTION SHOWS ORIGINAL CONDITION

PLATE 64.




ANSFONTEIN RIA LINE

PLATE 65.

idge repairs.

MASGRK IN BANK



f.l. Farmation Level.

h. Height of bank.

V--6'0"-+ Natural Ground

Cutting line of trench

DIMENSI PER CRIB PIERS

S 3' 20' 30' 50',	30 45 65 115	\$ 5.0 5.3 4.3 5.5	£ 3"	-1	N-0" wridth of pier = single crlb. 18-0" " = clouble " 16-0" " " = treble " 16-0"
7.5	180	5.6) OF T	0"	NA OF BAULES 4 of 16x8 or 2 of 14x14 or 2 of 18x9
L = Me ŧ = TT: ° = Of:	aximi ickne fset ir	pan is um loo ss of t n thick 5,10,20	oxd(li op of p eness o	o" oto, n	4 of 18x9' or 6 of 16x8' 2 of 18x8' 6 of 18'x9'

t'- Length of pier plus
yR.L

do

-Length of top of pier -Offset at each end o


respectively below For


do 20, 25,

C


D'

ŧ.







Officer in Charge: Lieut. G.R. Frith, R.E.
Working Party: 8th (Railway) Compactivitian masons and
Time taken 51 days.



Longth of Devid Maximum Grad Minimum Curv




ELEVATION OF TREST Scale 8 Feet - 1 Inch



PLAN OF DEVIATION.

Scale 8 Chains-1 Inch.




Officer in Charge: Lieut. G. Working Party: 8th (Rail

Civilian A

Time taken: 4 months.

BRONKHORST SPRUIT BRIDGE. ELANDSFONTEIN-NATAL LINE.

Scale_12 Feet=1 Inch.




Working Party: 5 Officers, 140 N.C.O.'s and Men R.E. 20 Infantry Platelayers. 500 Natives.
Time taken: 3 days, 18 hours. Officer in Charge: Capt. F. G. Fuller, R.E.

5 METRE CULVERT, KILOMETRE 401.
PRETORIA-DELAGOA BAY LINE.

TEMPORARY REPAIR.


Scale, 8 Feet= 1 Inch.



WILGE R. BRIDGE.

BRIDGE, WITH SPAN OF FOUR TRUSSED BEAMS, ON DEVIATION. PRETORIA-DELAGOA BAY LINE.

Scale-12 Feet=1 Inch.



LINE .

Considerable Wick was now


Foundations of

RT BRIDGE.

OA BAY LINE.


BRIDGE.

-1 Inch




βE.

NE.





BAY LINE.

ATION.



IR .











PLATE 78.

Officer in Charge: Lieut. C.N.North Portions of 10th Working Party: 12nd (Fortress)









TRESTLE.

Temporary bridge







TRESTLE.

KAAP R. BRIDGE, AVOCA.
PRETORIA—DELAGOA BAY LINE.
DAMAGED BRIDGE.

Scale—40 Feet=1 Inch.





Length of Deviation Maximum Gradient Minimum Ourre or A.G. Hunter Weston, R.E. did most of earthwork of deviation with:—


E. Field Troop R.E. and Infantry

t. H.A. Micklem, D.S.O.R.E. completed with:—

3 Officers, 87 Non-commissioned officers and Men.R.E.

30 Infantry Platelayers

300 Naires



Major A. G. Hunter-Westi carried out: Lieut H.A. Micklem D. S with 3 Officers, 87. 30 Infantry platela, 300 natives.






PLATE 8.3.





Officer in Charge : Capt. F. G. Faller, R.E.

Working Party: 60 R.E.


30 Infantry details.

300 Natives.

Time taken for bridge and 1 mile of deviation

BANK BRIDGE.
ELANDSFONTEIN-KLERKSDORP LINE.
SEMI-PERMANENT BRIDGE.

Scale-16 Feet=1 Inch.




Officer in Charge: Lieut. A. G. T. Cusins, R.E.

Working Party: 17 R.E.
74 Natives.
Time taken: 6 days.

Officer in Charge: Lieut. Verco Working Party: 11 Men R.P

130 Natives. 6 days.

Time taken: 6 day



BRIDGE AT KILOMETRE 204%

ELANDSFONTEIN-KLERKSDORP LINE

SEMI-PERMANENT BRIDGE.

Scale 8 Feet - 1 Inch.


25 Natives.

Officer in charge: Lieut. Vercoe, R.P.R.

Working Party: 11 Men R.P.R.

Time taken: I day.

A SIMILAR BRIDGE AT K.M. 209 HAS BEEN REPAIRED IN THE SAME MANNER.



FREDERIKSSTAD BRIDGE.


ELANDSFONTEIN-KLERKSDORP LINE.

SEMI PERMANENT BRIDGE.

Scale 8 Feet = 1 Inch.

Officer in Charge: Lieut Veroe, R.P.R. Working Party: 11 Men. R.P.R. 54 Natives

Time taken



- CONSTRUCTION -




PLATE 90.

